

## VAG Bypass device – EDC16,EDC15,ME7



Device can perform bypass of the immobilizer of the vehicles equipped with engine control units from BOSCH:

- EDC16x diesel engines 1.9 TDI, 2.0 TDI, 2.5 TDI, 2.7 TDI, 3.0 TDI, 4.0 TDI, 4.2 TDI, 5.0 TDI
- **EDC15x** diesel engines 1.9 TDI, 2.5 TDI
- ME7.x petrol engines 1.8, 2.0, 2.4, 2.6, 3.0, 3.5, 4.2

List of covered vehicles from function bypass of immobilizer (all vehicles are after year 2000):

Model	Year
Audi A2	All diesel engines
Audi A3/S3	All vehicles except 1.6 and 2.0TFSI
Audi A4/S4/RS4	All vehicles except FSI engines
Audi A6/S6/RS6	All vehicles except 2.0 TFSI
Audi A8	All from 2001 to 2008 except 3.3TDI and TFSI engine
Audi Allroad	All vehicles except 2.0 TFSI
Audi TT	From 2001 to 2004
Audi Q7	All 3.0TDI and 4.2TDI
Seat Alhambra	All with engine 1.8T, 1.9TDI, 2.0TDI
Seat Altea	All with engine 1.8T, 1.9TDI, 2.0TDI
Seat Altea XL	All with engine 1.8T, 1.9TDI, 2.0TDI
Seat Arosa	All diesel vehicles
Seat Cordoba	All with engine 1.8T, 1.9TDI
Seat Ibiza	All diesel vehicles
Seat Leon	All vehicles except FSI
Seat Toledo	All vehicles except FSI
Skoda Octavia	All vehicles except FSI
Skoda Octavia II	All vehicles except FSI
Skoda Scout	All vehicles except FSI
Skoda Praktik	all diesel vehicles
Skoda Roomster	all diesel vehicles
Skoda Fabia	all diesel vehicles
Skoda Superb	All vehicles up to 2008
Skoda Superb II (MY2008)	Not working
VW Bora	All vehicles except FSI
VW Caddy	All vehicles except FSI
VW EOS	All vehicles except FSI
VW Tiguan	All vehicles except FSI
VW Individual	All vehicles except FSI
VW Golf 4	All vehicles except 1.4 and 1.6 gasoline engines
VW Golf 5	All vehicles except FSI
VW Cross Golf	All vehicles except FSI, 1.6 gasoline engines
VW Jetta	All vehicles except FSI, 1.4 and 1.6 gasoline engines
VW Multivan/T5	all years
VW Passat B5	all years
VW Passat B6 - BOSCH	all years
VW Phaeton	all years

VW Polo	All vehicles up to 2008
VW T4	NOT WORKING !!!
VW LT	Only 2.5TDI
VW Touareg	all years
VW Touaran	All vehicles except FSI
VW Beetle	All vehicles